April 6 2009 L'Aquila (Abruzzo) Earthquake in Central Italy

Jonathan P. Stewart GEER Team Leader

Outline

- Team organization and management
- Source characteristics
- Ground motions
- Geotechnical aspects
 - Site effects
 - Landslides
 - Levees/embankments
 - Lake Sinizzio
- Technology applications

• GEER-funded:

- Stewart
- D. Scott Kieffer, U. Graz
- R.E. Kayen, USGS
- G. Biscontin, T. A&M



- GEER-funded
- Italians:
 - G. DiCapua, INGV
 - G. Scasserra, U. Rome
 - F. Silvestri, U. Naples
 - G. Lanzo, U. Rome
 - P. Tommasi, CNR-IGAG,Rome
 - A. Simonelli, U. Sannio




- GEER-funded
- Italians
- Non-Italian volunteers:
 - E. Button, ETH Zurich
 - G. Mylonakis, U. Patras
 - G. Athanasopoulos, U. Patras





- GEER-funded
- Italians
- Non-Italian volunteers
- Discussion points:
 - Italians' disposition
 - Local inclusiveness
 - FTP site/Clearinghouse
 - Training (mission, GEER vs. local)
 - Deployment issues
 - Always an Italian
 - Experience counts





Local Geology















Surface Rupture

- Some deformation reported:
 - Paganica
 - Poggio
 - Aterno
- Consensus: No SR from primary fault
- Controversial: Co-seismic origin of displacements near mapped faults




Surface Rupture











InSAR

















- 56 digital recordings
- Permanent displacement evident in L'Aquila –
 AQ* recordings on hanging wall.
- Analogue recordings?
- Preliminary site classifications in report
- Few sites with velocity profiles





Damage Level	Description	Marker Color
D0	No damage	
D1	Cracking of non-structural elements, such as dry walls, brick or stucco external cladding	
D2	Major damage to the non-structural elements, such as collapse of a whole masonry infill wall; minor damage to load bearing elements	
D3	Significant damage to load-bearing elements, but no collapse	
D4	Partial structural collapse (individual floor or portion of building)	
D5	Full collapse	











- Damage Patterns
- Landslides/Rockfalls





- Damage Patterns
- Landslides/Rockfalls







- Damage Patterns
- Landslides/Rockfalls
- Levees/embankments





- Damage Patterns
- Landslides/Rockfalls
- Levees/embankments
- Lake Sinizzio







Technology Applications

- Common GPS
- "Layering" capability in Google Earth (GE)
- GE on laptops in field
- Lidar